

# CERTIFICATE OF COMPLIANCE

**Certificate Number** E184471  
**Report Reference** E184471-20181015  
**Issue Date** 2020-JANUARY-03

**Issued to:** Solutions Industry & Building  
25 Rue Theophile Somborn  
57220 Boulay FRANCE

**This certificate confirms that  
representative samples of**

OUTLET BUSHINGS AND FITTINGS  
See Addendum Page for Models

Have been investigated by UL in accordance with the  
Standard(s) indicated on this Certificate.

**Standard(s) for Safety:**

UL 514B and CAN/CSA C22.2 No. 18.3-12 Standards for  
Conduit, Tubing, and Cable Fittings

**Additional Information:**

See the UL Online Certifications Directory at  
<https://iq.ulprospector.com> for additional information.

This *Certificate of Compliance* does not provide authorization to apply the UL Mark. Only the UL Follow-Up Services Procedure provides authorization to apply the UL Mark.

Only those products bearing the UL Mark should be considered as being UL Certified and covered under UL's Follow-Up Services.

Look for the UL Certification Mark on the product.



Bruce Mahrenholz, Director North American Certification Program  
UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>



# CERTIFICATE OF COMPLIANCE

**Certificate Number** E184471  
**Report Reference** E184471-20181015  
**Issue Date** 2020-JANUARY-03

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements.

USL, CNL: Liquid Tight Flexible Cord Connectors, Cat, Nos.:

C5225000 or 4220625, C5232000 or 4220632, C5240000 or 4220640, C5250000 or 4220650, C5263000 or 4220663, C5225040 or 4220725, C5232040 or 4220732, C5240040 or 4220740, C5250040 or 4220750, C5263040 or 4220763, C5325000 or 4220675, C5332000 or 4220677, C5340000 or 4220678, C5350000 or 4220679, C5363000 or 4220680, C5325040 or 4220775, C5332040 or 4220777, C5340040 or 4220778, C5350040 or 4220779, C5363040 or 4220780, C5048000, C5049000 or 4220348, C5048400, C5049400 or 4220360, C5148000, C5149000 or 4220448, C5148400, C5149400 or 4220460, C5420000 or 4220802, C5428000 or 4220803, C5420400 or 4220812, C5428400 or 4220813, C5225100 or 4220953, C5232100 or 4220954, C5240100 or 4220955, C5250100 or 4220956, C5263100 or 4220957, C5225140 or 4220973, C5232140 or 4220974, C5240140 or 4220975, C5250140 or 4220976, C5263140 or 4220977, C5325100 or 4220961, C5332100 or 4220962, C5340100 or 4220963, C5350100 or 4220964, C5363100 or 4220965, C5325140 or 4220983, C5332140 or 4220984, C5340140 or 4220985, C5350140 or 4220986, C5363140 or 4220987, C5048100, C5049100 or 4220910, C5048140, C5049140 or 4220920, C5148100, C5149100 or 4220930, C5148140, C5149140 or 4220940, C5420100 or 4220992, C5428100 or 4220993, C5420140 or 4220997, C5428140 or 4220998, C5225200 or 4264425, C5232200 or 4264432, C5240200 or 4264440, C5250200 or 4264450, C5263200 or 4264463, C5225240, C5232240, C5240240, C5250240, C5263240, C5325200, C5332200, C5340200, C5350200, C5363200, C5325240, C5332240, C5340240, C5350240, C5363240, C5420200, C5428200, C5420240, C5428240, C5225105, C5232105, C5240105, C5250105, C5263105, C5225145, C5232145, C5240145, C5250145, C5263145, C5325105, C5332105, C5340105, C5350105, C5363105, C5325145, C5332145, C5340145, C5350145, C5363145, C5048105, C5049105, C5048145, C5049145, C5148105, C5149105, C5148145, C5149145, C5420105, C5428105, C5420145, C5428145, C5225205 or 4264625, C5232205 or 4264632, C5240205 or 4264640, C5250205 or 4264650, C5263205 or 4264663, C5225245, C5232245, C5240245, C5250245, C5263245, C5325205, C5332205, C5340205, C5350205, C5363205, C5325245, C5332245, C5340245, C5350245, C5363245, C5412205, C5428205, C5420245, C5428245

Alternate Cat. Nos. are separated by "or".

USL, CNL: Dry Locations Flexible Cord Connectors, Cat, Nos.:

C5220000, C5320000, C5013000, C5113000, C5412000, C5220100, C5320100, C5013100, C5113100, C5412100, C5220200, C5320200, C5412200, C5220105, C5320105, C5013105, C5113105, C5412105, C5220205, C5320205, C5412205



Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>

